





Spectrum Astro Space Systems

Mission ICD Interface Change Notice (ICN)

ICN TITLE: SC-LAT MLI Blanket Interface		ICN NO. 097	PAGE 1 OF 3
ICD TITLE: LAT-SC ICD Rev C	ICD NUMBER: 1196-EI-Y46311-000	DATE: 7-26-05	
ORIGINATOR: Rich Belawski	ORGANIZATION: SLAC	PHONE: 650-926-5190	
REASON FOR CHANGE: The definition of the MLI interface between the LAT and SC is currently TBD. This ICN updates the ICD with the definition of where the SC MLI will attach to LAT hardware.			
BRIEF DESCRIPTION OF CHANGE: Delete page A9, rename A10 to A11 and add two new pages (A9, A10) to Appendix A with the MLI interfaces shown.			
RELATED ATTACHMENTS: See attached pages.			
BRIEF DISCUSSION OF IMPACT: No impact to either the LAT or SC.			
ORIGINATOR SIGNATURE:		DATE:	
APPROVAL SIGNATURES			
SPECTRUM ASTRO PROGRAM MANAGER / DATE		 9/28/05 INSTRUMENT PROGRAM MANAGER / DATE	
SPECTRUM ASTRO INSTRUMENT ENGINEER / DATE		 9/28/05 INSTRUMENT ENGINEER / DATE	
DISPOSITION OF CHANGE REQUEST:			
<input type="checkbox"/> ACCEPTED		<input type="checkbox"/> REJECTED	