




RECEIVED OCT 21 2004

APPROVED DEC 6 2004

 <h2 style="text-align: center;">GLAST Mission Interface Change Notice (ICN)</h2>		ICN No. 076
		SHEET <u>1</u> OF 4
ORIGINATOR: Rich Bielawski		PHONE: 650-926-5190
CHANGE TITLE: Use Discrete Monitor Spares for SIU Boot Status		DATE: 9-23-04
		ORG: LAT/SLAC
DOCUMENT NUMBER	TITLE	VERSION
1196-EI-Y46311-000	LAT-SC ICD	C
REASON FOR CHANGE: SIU boot status is helpful in ascertaining the health of the SIU.		
PROPOSED CHANGE: Change Figure 6-18 and Appendix B connector pin-out labels for JL-121 and JL-122 as per the following pages.		
INSTRUMENT IMPACT <input type="checkbox"/> Cost <input type="checkbox"/> Schedule	No Impact.	
SPACECRAFT IMPACT <input type="checkbox"/> Cost <input type="checkbox"/> Schedule		
ORIGINATOR SIGNATURE:		
APPROVAL SIGNATURES:		
Spectrum Instrument Interface Lead – Tim Morse		Spectrum Program Manager – Al Lepore
 Instrument Systems Engineer – Dick Horn		 Instrument Program Manager – Lowell Klaisner