

Appendix D: Connector Mate/Demate Log

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: GLAT 2206

Connector(s)	Authorized by Procedure & para or NCR	Date M/D/Y	Mate or De-mate M or D	Flight or Test F or T	Verify Power Off Emp. ID#	Pre-mate Inspect		ESD Bleed and Connector Mate		Final Inspect Fasteners Torqued, Witness Scribe applied	
						*Emp. ID#	QA	* Emp ID#	QA	* Emp. ID#	QA
BP PCI Connector 4	W03 1661	10/20/15	H	F	JBT	JBT	JBT	JBT	JBT	JBT	JBT
	W03 1661	10/20/15	D	F	JBT	JBT	JBT	JBT	JBT	JBT	JBT

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.