

Tower Electronics Module Stray Voltage Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION:

LAT 1773 (4122)

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power On	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & Para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
TC-0	100070	4/8/5	M	F	gav	gav	QA	gav	QA
TC-1									
TC-2									
TC-3									
TC-0									
DT-1									
DT-2									
DT-3									
DT-4									
DT-5									
DT-6									
DT-7									
DT-1									

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

LE 2
 QA
 4-12-05

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

LAT-TD-04097-03

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

CONNECTOR MATE / DEMATE

UNIT DESCRIPTION: LAT 1773

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect	
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	QA	*Emp. ID#	QA
JIC-0	120830	4/18/05	D	F	800	800	11542	800	11542
JIC-1									
JIC-2									
JIC-3									
JTI-0									
JTI-1									
JTI-2									
JTI-3									
JTI-4									
JTI-5									
JTI-6									
JTI-7									
JTI-8									
JTI-9									
JTI-10									

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.