

Appendix B Connector Mate/Demate Log

UNIT DESCRIPTION:

4LAT 1767 CONNECTOR MATE / DEMATE

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID# QA	*Emp. ID# QA	*Emp. ID# QA
JC-0	MBB30	6/11/15	M	F	XND	XND	XND	XND
JC-1								
JC-2								
JC-3								
DE-JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
JT-8								
JT-9								

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Note: This Mate/Demate log is a Microsoft Excel file embedded in the Microsoft Word version of this document. The file can be copied and pasted into a folder and then opened as an Excel worksheet.

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

Tower Electronics Module Electrical Interface Continuity and Isolation Test

The Excel Mate/Demate log form that is below is the actual Excel file imported into this word document. You can copy and paste it into a folder and then open it as an Excel worksheet.

UNIT DESCRIPTION: GLAT 1767 **CONNECTOR MATE / DEMATE**

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	MDY	M or D	F or T	Emp. ID#	* Emp. ID#	QA	* Emp. ID#
JC-0	WDBFD	6/20/5	D	F	SD	SD	QA	SD
JC-1								
JC-2								
JC-3								
JT-0								
JT-1								
JT-2								
JT-3								
JT-4								
JT-5								
JT-6								
JT-7								
J-1								
J-1								

* Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

Hard copies of this document are for REFERENCE ONLY and should not be considered the latest revision.

UNIT DESCRIPTION:

GAAT 176F

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power Off	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	Emp. ID#	Emp. ID#	Emp. ID#
IC-0	ISO 870	7/3/15	M	F	20	20	20	20
IC-1				F				
IC-2				F				
IC-3				F				
JT-0				F				
JT-1				F				
JT-2				F				
JT-3				F				
JT-4				F				
JT-5				F				
JT-6				F				
JT-7				F				
J-1				F				
JS-1				F				

*Personnel that is Mate/Demate certified.

Connector /Bracket R/D:

UNIT DESCRIPTION:

GLAT 176 T

Connector Mate/Demate Log

Connector(s)	Authorized by	Date	Mate or Demate	Flight or Test	Verify Power On	Pre-mate Inspect	ESD Bleed and Connector Mate	Final Inspect
Connector Reference Designator	Procedure & para or NCR	M/D/Y	M or D	F or T	Emp. ID#	*Emp. ID#	*Emp ID#	Fasteners Torqued, Witness Stripe applied
IC-0	MD 870	3/10/15	D	F	SA	SA	SA	SA
IC-1				F				
IC-2				F				
IC-3				F				
JT-0				F				
JT-1				F				
JT-2				F				
JT-3				F				
JT-4				F				
JT-5				F				
JT-6				F				
JT-7				F				
J-1				F				
JS-1				F				

*Personnel that is Mate/Demate certified.

Connector /Bracket

R/D: