


GLAST Large Area Telescope: LAT System Engineering


Pat Hascall
SLAC
System Engineering

hascallp@slac.stanford.edu
650-926-4266






Overview

- **ACD team has requested rerouting harness between the BEA and the bulkhead**
 - **Need for change presented by ACD team**
 - **Proposed change summarized in following charts**
- **This meeting will serve as an CCB**
 - **If the change is approved as an emergency change, the CR and DCN will follow**
 - **Preliminary list of impacted documentation**
 - LAT-SS-00363, ACD-LAT ICD
 - “LAT-DS-02139”, EMI Shield drawing with bulkheads and connector locations
 - LAT-TD-00890, LAT Instrumentation Plan
 - T/V Test Plan???
 - LAT-DS-02111, External Cables DAQ to BEA
 - Cable drawings for ACD instrumentation from BEA to EMI



+X Face, Current and Proposed





-X Face, Current and Proposed

