

RECEIVED MAR 16 2004

APPROVED MAR 26 2004



# GLAST Mission Interface Change Notice (ICN)

ICN No.  
043

SPECTRUMASTRO

SHEET 1 OF 16

ORIGINATOR: Rich Bielawski

PHONE: 650-926-5190

DATE: 2-18-04

CHANGE TITLE: Voltage Monitor Spare Use

ORG: LAT

DOCUMENT NUMBER	TITLE	VERSION
1196-EI-Y46311-000	LAT-SC ICD	B

**REASON FOR CHANGE:**

LAT has identified the need to use a portion of the existing voltage monitor spares in connectors JL-1, 2, 124, 125, 138 and 145. Also, the names need to change for the existing voltage monitors on connectors JL-1 and 2 to differentiate them from the new voltage monitors.

**PROPOSED CHANGE:**

See attached.

**INSTRUMENT IMPACT**

- Cost
- Schedule

None.

**SPACECRAFT IMPACT**

- Cost
- Schedule

**ORIGINATOR SIGNATURE:**

**APPROVAL SIGNATURES:**

Spectrum Instrument Interface Lead - Tim Morse

Spectrum Program Manager - Al Lepore

Instrument Systems Engineer - Dick Horn

Instrument Program Manager - Lowell Klaisner