

Inside the Van de Graaff – 4/24/03

For the past couple of weeks the VG has been making 50-60 μA of column current but zero beam current...so we opened up the VG tank. Notice that the belt has gone off center and self destructed.

