



Review of nonconformancies

SWX60743 01009

Leakage current scan



Optical Inspection: just two little spots





SWX60743 0095

Leakage current scan




Optical inspection: scratch near the center of the detector.



SWX60745 01077


Leakage current scan



Optical inspection: nothing particular. Just a lot of dust and particulate around and a very little scratch.

SWX60745 01087


Leakage current scan




Optical inspection: nothing at all.

SWX60747 01135


Leakage current scan



Optical inspection: bottom left corner missing:
there is a scratch.



SWX60709 00736



Missing bottom left corner.